



1/6




Fig. 1




Fig. 2




Fig. 3A




Fig. 3B




Fig. 4




Fig. 5



IMPLANTABLE PRESSURE SENSORS AND METHODS FOR MAKING AND USING THEM  
Lone Wolinsky, et al  
09/888,272

4/6




Fig. 6




Fig. 7

MAY 17 2004



5/6




Fig. 8A




Fig. 8B




Fig. 9